ECS Configuration Change Request

CCR No. 96-0549	**Logged Date** 05/28/95	**Rev.**	**Request Type** CCR

Priority Routine ☒ Urgent ☐ Emergency ☐	**Affected Release** A	**Change Class**

Title (description)
AMASS 4.5.1_1 Upgrade

Documents Affected	**Source Nos** (RID, NCR, etc.) **or Tech Reference**
VCATS	Bruce Clark, EDS
Release A Baseline	Don Brown, DSS, DCB
	Richard Gorsky, Rel A

RTM Change   ☐   **Start New Baseline** ☐

Problem
The current version of the AMASS FSMS software (4.5) installed in the EDF (on drpe2sgi) needs to be upgraded to version 4.5.1_1 to accommodate microcode updates required by the EMASS 8590 tape drives. The microcode updates to the 8590 tape drives are required to correct problems that IBM has identified with the 8590 drives.

Proposed Solution
Schedule the upgrade of the AMASS FSMS software to version 4.5.1_1 in the EDF for the week of June 3, 1996. Concurrently schedule the upgrade of the EMASS 8590 tape drive microcode. Both upgrades are expected to require a total downtime of two days.

Impact Analysis:

Organizations Affected: BOO ☐   Contracts ☐   ESO ☐   FOS ☐   M&O ☒

QA ☐   Rel. A ☒   Rel. B ☐   Rel. IR1 ☐   MRS ☐   SMO ☐   Subconts ☐

Other _____

Cost: None ☒   Small ☐   Medium ☐   Large ☐
                    (Not exceeding $100,000)   ($100,000 to $500,000)   (Over $500,000)

Schedule: None ☒   Other

Additional LOC _____   Man-Months _____

Materials

Originator Richard Gorsky _____   _____
                                              Signature   Date

Office Release A   Office Manager   _____
                                              Signature   Date

Disposition   Approved ☐   Approved w/Comment ☐   Forward ☐   Disapproved ☐
Comments:
CCB Chairperson   _____
Signature   Date